



2022 Honda Accord Sport VIN: 1HGCV1F31NA094950 License Plate: 9EFZ860 Mileage In: 21,375 Mileage Out: 21,433

Pre Calibration Dynamic Systems Verification

Inspected: 02/03/2024 Completed: 02/02/2024

	Item	Green	Yellow	Red	N/A
1	Walkaround Inspection	~			
	Note/Recommendation: Dash photo (make sure mileage, fuel leve visible) Exterior photos (move vehicle to suitable location) Interior photos (include any missing/damaged components)	l, and any malfur	ction lights,	/messages	are
	Note:				
	Green: Vehicle is free of defects & ready for driving Yellow: Vehicle has repair defects or missing parts, see photos Red: Vehicle cannot be driven	3.05			



2	Rear Back Up Camera (can include front grille camera for non-AVM systems)
	Note/Recommendation: Includes photos of camera & monitor view (turn steering wheel to display active guidelines) Note: Green: System is fully functional and behaves normally Yellow: There is a problem with the sensor that requires correction before calibration Red: System does not operate due to malfunction Image:
3	Rear Parking Sensors (Sonar)
	Note/Recommendation: Includes photos of sensors on rear bumper cover Note: Green: System is fully functional and behaves normally Yellow: There is a problem with the sensor that requires correction before calibration Red: System does not operate due to malfunction
4	360 Camera/Surround View
	Note/Recommendation: Includes photos of monitor view and cameras (side mirrors & front grille) Note:



	Green: System is fully functional and behaves normally Yellow: There is a problem with the sensor that requires correction befor Red: System does not operate due to malfunction	e calibratio	n		
5	Rear Side Radar (BSM, RCTA)				~
	Note/Recommendation: Includes photos of indicator lights (side mirrors	;)	2	2	
	Note:				
	Green: System is fully functional and behaves normally Yellow: There is a problem with the sensor that requires correction before Red: System does not operate due to malfunction	e calibratio	n		
6	Front Parking Sensors (Sonar) and/or Front Camera				~
	Note/Recommendation: Includes photos of sensors on front bumper co	ver			
	Note:				
	Green: System is fully functional and behaves normally Yellow: There is a problem with the sensor that requires correction befor Red: System does not operate due to malfunction	e calibratio	n		
7	Front Radar (can include ACC, AEB, FCW)			~	
	Note/Recommendation: Includes photos of front radar & ACC / FCW cor	ntrols if equ	lipped		
	Note: If equipped w/ AEB and/or FCW it is currently unsafe to test.				
	Green: System is fully functional and behaves normally Yellow: There is a problem with the sensor that requires correction before Red: System does not operate due to malfunction	e calibratio	n		
8	Front Side Radar (can include FCTA, Evasion Assist, Auto Lane Change)				~
	Note/Recommendation: Includes photos of controls if equipped				
	Green: System is fully functional and behaves normally Yellow: There is a problem with the sensor that requires correction before Red: System does not operate due to malfunction	e calibratio	n		



9	Windshield Camera (can include ACC, AEB, FCW, LDW, LKA)			~	
	Note/Recommendation: Includes photos of windshield camera, glass logities if equipped	go, and AC	C/FCW/Lan	e Departure	e controls
	Note: If equipped w/ AEB and/or FCW it is currently unsafe to test.				
	Green: System is fully functional and behaves normally Yellow: There is a problem with the sensor that requires correction before Red: System does not operate due to malfunction Image: System Correction for the sensor that requires correction before Image: System correction before Imag	e calibratio	n		
10	Coolant Levels Check	~			
	Note/Recommendation: Before departing, check both engine and hybrid "Min-Max" indicators on side of reservoir. Includes photos of coolant tank		ystem cool	ant levels to	o proper
	Note: Green: Vehicle is ready for driving Yellow: Vehicle is low or overfilled Red: Vehicle cannot be driven Was not able to visually inspect.				
11	Green: Vehicle is ready for driving Yellow: Vehicle is low or overfilled Red: Vehicle cannot be driven	✓			
11	Green: Vehicle is ready for driving Yellow: Vehicle is low or overfilled Red: Vehicle cannot be driven Was not able to visually inspect.	✓ re sure Neg	ative and P	ositive are f	ūlly
11	Green: Vehicle is ready for driving Yellow: Vehicle is low or overfilled Red: Vehicle cannot be driven Was not able to visually inspect. IVUSTION OF THE OPENING OF THE OPE	✓ re sure Neg	ative and P	ositive are f	ūlly
11	Green: Vehicle is ready for driving Yellow: Vehicle is low or overfilled Red: Vehicle cannot be driven Was not able to visually inspect. Isource of the state	✔ re sure Neg	ative and P	ositive are f	ūlly



Calibration Prep

Completed: 02/02/2024

	Item	Green	Yellow	Red	N/A
1	Fuel Weight Compensation	~			
	Note/Recommendation: Includes calculating the amount of fuel needed weights over the fuel tank to simulate a full tank of fuel, and a photo of the customer items from vehicle if present to un-load vehicle, check that span Fuel Capacity: 14.8 Fuel Level: 1/4 full Weight Added: 30Kg Green: Fuel compensation was completed Yellow: Vehicle on empty, fuel was added for test drive Red: Fuel system issue	ne weights	in the vehicl	le. Remove	
2	Tire Inflation & Tread Depth	~			
	Note/Recommendation: Includes inflating tires to specified pressures, ti jamb), Laser-scan each tire for 3-point tread depth measurements, and vi tires are hot, the pressure should be +3psi higher than cold tire pressure tread depth.	sual inspe	ction. Ìf vehi	icle is drive	n and
	Compensation Pressure: +3psi				
	Green: All tires are in good condition with few minor defects Yellow: There is one or more tires that has a moderate concern Red: There is a major tire concern that is unsafe for driving				





3	Body Height Measurements	~			
	 Note/Recommendation: Includes height measurements at all four wheele in service information. Front L: 690 Front R: 699 Rear R: 713 Rear L: 709 Green: All measurements are within specifications (or less than 10mm of Yellow: Measurements are not to OE specification due to vehicle modification Red: Measurements are not to OE specification due to damage or susper 	lifference si ations	ide-to-side)	-	ndicated
	Totals	3	0	0	0

Post Calibration Dynamic Systems Verification

Completed: 02/03/2024

	Item	Green	Yellow	Red	N/A
1	Walkaround Inspection	~			
	Note/Recommendation: Dash photo (milage and all malfunction lights & Exterior photos (move vehicle to suitable location) Interior photos (include any missing/damaged components)Image: the state of	messages	are not pre	esent)	



2	Rear Back Up Camera (can include front grille camera for non-AVM systems)
	Note/Recommendation: Includes full system function test
	Green: System is fully functional and behaves normally Yellow: Calibration performed but see note
3	Rear Parking Sensors (Sonar)
	Note/Recommendation: Includes full system function test
	Green: System is fully functional and behaves normally Yellow: Calibration performed but see note
4	360 Camera/Surround View
	Note/Recommendation: Includes full system function test
	Green: System is fully functional and behaves normally Yellow: Calibration performed but see note



5	Rear Side Radar (can include BSM, RCTA)				~
	Note/Recommendation: Includes full system function test				
	Green: System is fully functional and behaves normally Yellow: Calibration performed but see note				
6	Front Parking Sensors (Sonar) and/or Front Camera				~
	Note/Recommendation: Includes full system function test				
	Green: System is fully functional and behaves normally Yellow: Calibration performed but see note				
7	Front Radar (can include ACC, AEB, FCW)	~			
	Note/Recommendation: Includes full system function test				
	Note: If equipped w/ AEB and/or FCW it is currently unsafe to test.				
	Green: System is fully functional and behaves normally Yellow: Calibration performed but see note				
8	Front Side Radar (can include FCTA, Evasion Assist, Auto Lane Change)				~
	Note/Recommendation: Includes full system function test				
	Green: System is fully functional and behaves normally Yellow: Calibration performed but see note				
9	Windshield Camera (can include ACC, AEB, FCW, LDW, LKA)	~			
	Note/Recommendation: Includes full system function test				
	Note: If equipped w/ AEB and/or FCW it is currently unsafe to test.				
	Green: System is fully functional and behaves normally Yellow: Calibration performed but see note				
	Totals	4	0	0	5

Reports

Inspected: 02/02/2024 Completed: 02/02/2024

	Item	Green	Yellow	Red	N/A
1	Calibration & Diagnostic Reports	~			



Note/Recommendation: Diagnostics: Includes reviewing the collision work order and a scan of all vehicle systems before work is started and after all work is completed.

Note:

Green: All trouble codes cleared & did not return after test drive Yellow: There are one or more remaining trouble codes of minor concern Red: There are one or more remaining trouble codes of moderate to major concern

Calibrations: Includes screenshots of OEM diagnostic software calibration process, photos of static calibration setup, and/or test-drive file for dynamic calibrations. Calibration screenshots are included in the diagnostic report if using universal scan tool.

Note:

Green: All calibrations completed successfully Yellow: One or more calibrations has an issue that requires correction Red: Calibration cannot be performed due to damaged/missing/incorrect component

